

## Specifications

Model	7000	7000S	7500	7500PS	8000	8000S	8500	8500S	9000	9000S
	7000PS	7000S(PS)			8000PS	8000S(PS)			8500PS	8500S(PS)
Power source	30VDC									
Torque range Kgf-cm / lbf-in	7-20 / 6.1-17.4		7-30 / 6.1-26.0		12-30 / 10.4-26.0		12.0-40.0 / 10.4-34.7		20.0-50.0/17.3-43.4	
Torque accuracy	±3%									
No load speed/ rpm	700	1000	1000		550	1000	700	1000	500	650
Torque setting	Stepless									
Available Screw	Machine screw mm / in		3.0-5.0 / 0.12-0.20		3.5-5.0 / 0.14-0.20		3.5-5.5 / 0.14-0.22		4.0-6.0/0.16-0.24	
	Machine screw mm / in		2.6-4.0 / 0.10-0.16		3.0-4.0 / 0.12-0.16		3.0-4.5 / 0.12-0.18		3.5-5.0/0.14-0.20	
Weight g / lb	670 / 1.47 , 740/1.6 (PS)									
Length mm / in	265 / 10.4, 269/10.6 (PS)									
Available bit shank	5 φ/5mm hex shank · 1/4" hex shank									
Power consumption	60									
Available power supply	APS-30,APT70(5P)(ASA-7000/8000) · APS-30U,APS-70S(6P)(ASA-7500/8500/9000)									
Clutch impact	Just one time when torque up									

## Outline (this drawing applies only to 1/4" hex. bit shank screwdrivers)

